



Digital 6000

L 6000 - Firmware version 3.0.2

For conformity, consistency and compatibility reasons, we strongly recommend upgrading the L 6000 to the new release.

Features

- We support a second source for the BA 61 production

Bug fixes

- Solved an issue that an inserted BA 70 over 45 °C will not be charged
- Solved an issue that an inserted BA 70 under 0 °C the „too warm“ warning is now eliminated

Firmware update

- The L 6000 firmware update requires the Sennheiser Wireless Systems Manager software:
www.sennheiser.com/wsm



Previous Releases

L 6000 - Firmware version 3.0.1

Features

- Support of LM 6070 charging module for BA 70 rechargeable battery pack.

Notes

- No “time to empty” parameter in WSM for BA 70 rechargeable battery pack is supported.

L 6000 - Firmware version 2.0.12

Features

- Bug fixes and optimizations

L 6000 - Firmware version 2.0.11

Features

- Improved charging behavior for BA 62
- Bug fixes and optimizations

L 6000 - Firmware version 2.0.10

Features

- BA 62: Missing “time to full” parameter in WSM implemented
- Bug fixes and optimizations

L 6000 - Firmware version 2.0.8

Features

- Support of LM 6062 charging module for BA 62 rechargeable battery pack
- Bug fixes and optimizations

Known issues

- No “time to full” parameter in WSM for BA 62 rechargeable battery pack

L 6000 - Firmware version 1.2.1

Features

- Problem with phantom error messages concerning the fan system has been resolved.