



## Digital 6000

### L 6000 - Firmware version 3.0.1

For conformity, consistency and compatibility reasons, we strongly recommend upgrading the L 6000 to the new release.

### Features

- Support of LM 6070 charging module for BA 70 rechargeable battery pack.

### Notes

- No “time to empty” parameter in WSM for BA 70 rechargeable battery pack is supported.

### Firmware update

- The L 6000 firmware update requires the Sennheiser Wireless Systems Manager software: [www.sennheiser.com/wsm](http://www.sennheiser.com/wsm)



## Previous Releases

### L 6000 Firmware version 2.0.12

#### Features

- Bug fixes and optimizations

### L 6000 - Firmware version 2.0.11

#### Features

- Improved charging behavior for BA 62
- Bug fixes and optimizations

### L 6000 - Firmware version 2.0.10

#### Features

- BA 62: Missing “time to full” parameter in WSM implemented
- Bug fixes and optimizations

### L 6000 - Firmware version 2.0.8

#### Features

- Support of LM 6062 charging module for BA 62 rechargeable battery pack
- Bug fixes and optimizations

#### Known issues

- No “time to full” parameter in WSM for BA 62 rechargeable battery pack

### L 6000 - Firmware version 1.2.1

#### Features

- Problem with phantom error messages concerning the fan system has been resolved.