



## TeamConnect Ceiling Medium

Ceiling microphone array

### Firmware Update

- The TeamConnect Ceiling Medium firmware update requires the Sennheiser Control Cockpit software: [www.sennheiser.com/control-cockpit-software](http://www.sennheiser.com/control-cockpit-software)

### Firmware version 1.2.7 - Release Date 2023-10-23

- Fix broken firmware update for devices which never received an update before

### Previous Releases

#### Firmware version 1.2.5 - Release Date 2023-09-19

- The internal operating system has been updated.
- The internal handling of continuous beam angle data polling has been fixed.
- In case of Dante port has no IPv4 address, the address is displayed as '0.0.0.0'.
- The property 'maxLength' has been removed from timezone in '/api/device/time'.
- The default setting of '/api/audio/outputs/analog' has been fixed to 'LocalOutput'.
- The response on invalid strings for device name, location and position are returned as '400' now.
- An active termination is applied to all subscriptions in case of IP address change, factory reset and reboot.

#### Firmware version 1.2.3 - Release Date 2023-06-29

Initial Customer Release v.1.2.3